

JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

October 31, 2006

Renee' Quinton, Administrator Quinton Manor 3440 S Yellowstone Highway Idaho Falls, ID 83402

License #: RC-175

Dear Ms. Quinton:

On August 22, 2006, a life safety code survey was conducted at Quinton Manor. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Eric Mundell, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

ERIC MUNDELL

Team Leader

Health Facility Surveyor

Facility Fire, Life Safety, and Construction Program

EM/slc

c:

Mark Grimes, Supervisor, Facility Fire, Life Safety, and Construction Program



HEALTH & WELFARE

JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

September 6, 2006

Renee' Quinton, Administrator Quinton Manor 3440 S Yellowstone Highway Idaho Falls, ID 83402

Dear Ms. Quinton:

On August 22, 2006, a survey was conducted at Quinton Manor. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by September 21, 2006.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

Jul Bof FOR

MG/slc

Enclosure

(X6) DATE

Bureau of Facility Standards

(X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING 01 - ENTIRE BUILDING B. WING 13R175 08/22/2006 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 3440 S YELLOWSTONE HIGHWAY **QUINTON MANOR** IDAHO FALLS, ID 83402 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PREFIX (X5) COMPLETE ID (EACH DEFICIENCY MUST BE PRECEEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE **PREFIX** DATE CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) R9999 R9999 Initial Comments The facility was found to be in substantial compliance with the fire and life safety standards of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on August 22, 2006. The surveyors conducting the survey was: Eric Mundell Team Leader Health Facility Surveyor Mark P. Grimes Health Facility Surveyor Bureau of Facility Standards

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM 6999 5S5221 If continuation sheet 1 of 1

TITLE



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

ASSISTED LIVING Non-Core Issues Punch List

	<u>.</u>			
Facility Name		Physical Address	Phone Number	
Quintan Manue		3440 Yellow Stone +	typinay 208524	1958
Administrator		City	ZIP Code	
Konce Quinter		Idaho Fulla	S3 VO 2 Survey Date	·
Survey Team Leader		Survey Type	Survey Date	
Eric mundell		FLS	8/22/	06
NON-CORE ISSUES				
ITEM RULE#		DESCRIPTION		DATE RESOLVED
, 16.03.22.415.03	Fin E. Larish	: Two extinguishes	were lacked in horse	10/17/06
2 16.03.72.250.07	The same of the sa	and the same of th	1	10/19/06
	side of the 5	tops at the sleeping	rums that are	, Em
	occupied and	at the Kitchen and a	ctivity vem steps	9/22/02
3 16.03.22.750.01	Audrills: Fire	dills were not decum	ated as being held	<u> </u>
The state of the s	for the prievie	45 12 months		
c/ 16.03 22.750.05	h. Fire alaim test	: Then was no Cour	restation of months	4 9/22/06
	testing of the	fire alarm.	<u> </u>	En
5 16.03.72, 50.04	e. The fre wt	inguishes were not do	cumented as tested	9/22/2
	monthly, Then	were no monthly the	ieles.	1 En
6 16.03.22.750.00	Sprinkler System	: The aprinkler system	un not tested	9/22/4
25		equired Documentat	in are not availabl	1. 1. 1.
7 16-03.22.750.02	a. Fire Alarm:	The time alarm applian	, was not	9/20100
	decumented as	being inspected by a	Defensional busines	22
	on an annual	barri.		
Response Required Date	Signature of Facility Representative	· 4		
September 22, 2006	X Squee of	Jelse City		